## Portable Multiparameter Meter with GPS

## **Features**

Display from 1 to 12 parameters
Field replaceable sensors
Auto-recognition of all sensors
Optional autonomous logging probe
Rugged probe with stainless steel tip
Fast Tracker™−Tag I.D. System
Built-in barometer
Graphic LCD with backlight
PC connectivity
Meter accepts both alkaline and
rechargeable batteries



## **Measures**

pH/ORP/ISE EC/TDS/Resistivity/Salinity/ Seawater Specific Gravity Turbidity Dissolved Oxygen Temperature Atmospheric Pressure

HENNE



## w HI 9829 Kits 6.24pH 202.70RP 12.7 50.2%D0 14.7



